

SITE INSPECTION REVIEW FORM

SITE NAME: Crescent Lighting, Inc.

CITY, STATE: Barrington, New Jersey

ALIASES: None

CERCLIS I.D.#: NJD 980774467

FISCAL YEAR & QUARTER FOR SCAP: ~~4th Quarter FY '91 SI~~ *FY '92 / 1st Q SI*

CONTRACTOR RECOMMENDATION: No Further Remedial Action Planned *AGB 12/23*

EPA RECOMMENDATION: No Further Remedial Action Planned

PA METHOD SCORE = 50.48

WAS SAMPLING CONDUCTED BY CONTRACTOR? Yes, 5 surface soil & 2 subsurface soil samples.

COMMENTS:

The facility was cited by NJDEP for poor housekeeping practices that resulted in stained soil. ECRA subsequently requested and performed a clean-up resulting in the removal of contaminated soil. While the clean up was reported complete, there were no post remediation analytical results to evaluate adequacy of clean up.

Lubricating oils, waste solvents and metal shavings are generated on site, and drummed in 55 gallon containers prior to disposal. There is a 250 gallon tank used for on site storage of oil.

PAHs (20,000 ppb), di-n-butylphthalate (880 ppb), bis(2-ethylhexyl)phthalate (4000 ppb), aroclor-1254 (530 ppb) and pesticides (51 ppb) are present. Discharge to groundwater is likely, however there is a major confining layer between the site and wells of concern.

There are no primary targets identified as being impacted by this site. However there is a secondary target population for drinking water which should be considered. Sampling of groundwater should be performed to confirm or deny the presence of contamination.

REVIEWER:

Phil Guarraia

Phil Guarraia 12/23/91

